DEUTSCHLAND



PATENTAMT

②1) Aktenzeichen: 2 Anmeldetag:

P 38 03 388.7 2. 2.88

(43) Offenlegungstag: 10. 8.89



(1) Anmelder:

Sieger, Josef, 5010 Bergheim, DE

2 Erfinder: gleich Anmelder

(54) Heulstab

Mittels zweier 1,5 Volt Batterien wird über einen Motor ein Flügelrad getrieben, welches über Schlitze in einem stabförmigen Gehäuse Luft ansaugt, verdichtet und durch eine Heuleinrichtung auspreßt. Der Heulstab kann leicht an schwer zugänglichen Stellen mitgeführt werden oder, mit individuell zugeordneter Tonhöhe, zur Erkennung von Personen, Personengruppen oder zur Mitteilung von Ereignissen dienen.

Beschreibung

Beim Verschließen von Großkesseln, Großbehältern, Gas oder Wasser führenden Rohrleitungen u. dgl. nach einer Reparatur muß mittels einer von Hand anzutreibenden Heulsirene ein Warnton abgegeben werden. Dabei ist nachteilig die Unhandlichkeit der Sirene und der manuell vorzunehmende Antrieb, insbesondere deshalb weil die Sirene oft an schwer zugänglichen Stellen mitgeführt werden muß.

Mit der Erfindung soll deshalb die Aufgabe gelöst

werden, diesen Nachteil zu beseitigen.

Diese Aufgabe wird mit der im Patentanspruch 1 angegebenen Erfindung gelöst.

Ein Ausführungsbeispiel der Erfindung wird nachste- 15

hend anhand einer Zeichnung beschrieben.

Mittels zweier 1,5 Volt Batterien (5) wird über einen Motor (4) ein Flügelrad (2) getrieben, welches über Schlitze (3) im Stabgehäuse Luft ansaugt, verdichtet und durch eine Heuleinrichtung (1) auspreßt.

Der Heulstab kann in verkleinerter Ausführung auch am Körper getragen werden und als Signalquelle dienen zur Abschreckung von Gegnern oder Herbeirufung von Hilfe oder, mit individuell zugeordneter Tonhöhe, zur Erkennung von Personen, Personengruppen oder zur 25 akustischen Mitteilung von Ereignissen.

Patentansprüche

1. Tragbare Sirene, dadurch gekennzeichnet, daß 30 die Sirene in einem stabförmigen Gehäuse angeordnet und durch einen batteriegespeisten Elektromotor angetrieben wird.

2. Tragbare Sirene nach Anspruch 1, dadurch gekennzeichnet, daß die Batterien in dem stabförmi-

gen Gehäuse angeordnet sind.

40

45

50

55

60

65


- Leerseite -

3803388

Nummer: Int. Cl.⁴: Anmeldetag: Offenlegungstag: 38 03 388 G 10 K 7/04 2. Februar 1988 10. August 1989

3*

Fig.: 2::0:



908 832/255

DERWENT-ACC-NO: <u>1989-234950</u>

DERWENT-WEEK: 198933

COPYRIGHT 2005 DERWENT INFORMATION LTD

TITLE: Rod-shaped <u>portable</u> warning or recognition <u>siren</u> -

contains battery-powered electric motor driving blade

wheel

INVENTOR: SIEGER, J

PATENT-ASSIGNEE: SIEGER J[SIEGI]

PRIORITY-DATA: 1988DE-3803388 (February 2, 1988)

PATENT-FAMILY:

PUB-NO PUB-DATE LANGUAGE PAGES MAIN-IPC

DE 3803388 A August 10, 1989 N/A 003 N/A

APPLICATION-DATA:

PUB-NO APPL-DESCRIPTOR APPL-NO APPL-DATE

DE 3803388A N/A 1988DE-3803388 February 2, 1988

INT-CL (IPC): G10K007/04

ABSTRACTED-PUB-NO: DE 3803388A

BASIC-ABSTRACT:

The motor batteries are located in the rod-shaped casing. The batteries may be two 1.5v type (5). The motor (4) dirves a fan blade wheel (2) that sucks in <u>air</u> through slits (3) in the casing, compresses the <u>air</u> and forces it through the part (1) generating the <u>siren</u> sound.

USE/ADVANTAGE - Warning from places presenting difficult access, e.g. gas or water pipes upon closure of large boilers or large containers. Calling for help or scanning aggressor. Identification of individuals or groups. Acoustically informing of occurrence of event.

CHOSEN-DRAWING: Dwg.1/1

TITLE-TERMS: ROD SHAPE **PORTABLE** WARNING RECOGNISE **SIREN** CONTAIN BATTERY POWER

ELECTRIC MOTOR DRIVE BLADE WHEEL

DERWENT-CLASS: P86 W05

EPI-CODES: W05-A02; W05-B01D;

SECONDARY-ACC-NO:

Non-CPI Secondary Accession Numbers: N1989-178991

This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:	
	☐ BLACK BORDERS
	☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
	☐ FADED TEXT OR DRAWING
	☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
	SKEWED/SLANTED IMAGES
•	☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
	GRAY SCALE DOCUMENTS
	LINES OR MARKS ON ORIGINAL DOCUMENT
	REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY

IMAGES ARE BEST AVAILABLE COPY.

□ OTHER:

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.